



CRYSTORAMA LIGHTING




ASSEMBLY INSTRUCTION MODEL #ROX-A9006-GA


Drawing (1)




Drawing (2)



WARNING:




Electrical Danger



Turn Power off

All electrical components must be installed by a licensed electrician in accordance with the National Electric Code and the appropriate local electrical codes.



You will need 6-Candelabra
40 Watts Recommended 60 Watts Max.
USE LED BULBS FOR EXTENDED USE
THIS FIXTURE IS DRY RATED

How to Install:

1. Screw the loop (1) onto the Frame (2).
2. Install the Bulb (3) into the Socket (4).
3. The canopy of the fixture can now be mounted to the ceiling by following instruction **Drawing 2**.
4. Hook the Crystal Ball (5) to the bottom of the Ball Finial (6).

Bulb replacement:

1. Install the Bulb (3) into the Socket (4).

WARNING: This product can expose you to Lead which is known to the state of California to cause cancer and/or birth defects or reproductive harm. For more information go to www.P65Warnings.ca.gov

CRYSTORAMA LIGHTING



ASSEMBLY INSTRUCTION MODEL #ROX-A9006-GA

Part Number

- A. (1) Mounting Hardware
- B. (1) Canopy; w5"x h0.75" (XFW9003GACAN5IN)
- C. (1) Collar Ring
- D. (1) Collar Loop
- E. (2) Link
- F. (1) Chain ; w4.2mm (XFW9003GACHA4.2MM)
- G. (1) Loop
- H. (1) Frame
- I. (1) Ball Finial (XFW9000GAFIN)
- J. (6) Socket (H2")
- K. (1) Crystal Ball; w2"x h3.15" (XFW9006GACRY2IN)

